
2026

© Beward R&D Co., Ltd

BEWARD Intercom

Software Version History



www.beward.net

SEC.RU | Короткий путь к информации
Скачано с sec.ru

Version 2.7.0.50696 (03.06.2026)

New features

- Added support for device user access levels.

System requirements changes

- Starting with this version, the software requires .NET Framework 4.8. This version of .NET Framework is already installed in Windows 10/11 if automatic updates are enabled. The software installer will automatically download and install .NET Framework 4.8 in older versions of Windows, if it is needed (Internet connection is required). If Internet connection is missing on the target computer, please, install .NET Framework 4.8 manually using a standalone installer, which can be downloaded from Beward or Microsoft web site.
- Starting with this version, Windows 8 is no longer supported (except Embedded edition). Supported OS versions are: Windows 7 SP1, Windows 8 Embedded, Windows 8.1, Windows 10, Windows 11.

Version 2.6.0.43797 (28.04.2023)

Integration

- Intercom model DS07P-LP was integrated with firmware 3.1.0.0.2.27, build date 16.01.2023.
- Firmware 3.1.0.0.7.18 (build date 22.11.2022) was integrated for model DS06A.

New features

- Added the ability to receive video and audio from device during an incoming call via SIP before the call is accepted (Early Media).

Version 2.5.0.41941 (06.07.2022)

Integration

- Intercom model BVA1306MPA was integrated with firmware 3.1.8.1.1.25.2, build date 24.12.2021.
- Firmware 3.1.0.0.7.18 (build date 04.05.2022) and 3.1.0.0.1.25 (build date 04.05.2022) was integrated for model DS06A.
- Three-channel controller NC315P was integrated.

Version 2.4.0.40448 (19.11.2021)

Integration

- Intercom model DS85006MP was integrated with firmware 3.1.1.3.1.25.5, build date 02.09.2020.

New features

- Settings and call log archive may be kept during uninstall.

Version 2.3.6.37871 (28.07.2020)

Integration

- Intercom model DSN06PS was integrated with firmware 3.1.15.0.6.18.22.

Version 2.3.5.37043 (19.03.2020)

Integration

- Intercom model DP303M was integrated with firmware 3.1.8.1.6.18.1, build date 07.11.2019.
- Firmware 3.1.0.0.5.17 (build date 27.11.2019) was integrated for model DK103M.

SEC.RU | Короткий путь к информации Скачано с sec.ru

New features

- Added the ability to select audio playback and recording devices.

Version 2.3.4.36590 (04.12.2019)

Integration

- Firmware 3.1.0.0.1.25.33 was integrated for model DS06A.

New features

- Added support for talk mode in G.726 format.

Version 2.3.3.35805 (25.07.2019)

New features

- Added the ability to select the local IP address and port for SIP.

Version 2.3.2.34655 (11.01.2019)

New features

- Added incoming SIP calls support in P2P mode.

Version 2.3.1.34471 (13.12.2018)

Integration

- Intercom model DS06A(P) was integrated with firmware 3.1.0.0.6.18, build date 09.11.2018.

Version 2.3.0.24 (30.08.2018)

New features

- Added support for SIP intercoms:
  - receiving incoming calls;
  - receiving video;
  - two-way audio communication;
  - doors opening.

Version 2.2.11.4 (28.06.2018)

System requirements changes

- Starting with this version, the software requires .NET Framework 4.6.1. Full version of the installer is required to upgrade the software.
- Starting with this version, Windows XP and Vista are no longer supported. The minimal supported OS version is Windows 7 SP1.

Changes

- The application data directory, which stores logs, settings and the call records archive, was moved to ProgramData\BEWARD.

Version 2.2.10.5 (19.12.2017)

Integration

- Added support for multi user door stations connected via IP portal DK103M (firmware 3.1.0.0.3.18).

SEC.RU | Короткий путь к информации Скачано с sec.ru

Version 2.2.9.3 (26.09.2017)

- Bug fixes and stabilization.

Version 2.2.8.9 (27.04.2017)

Integration

- IP portal DK103M with Wi-Fi and 4G support was integrated (firmware 3.1.0.0.3.18).
- Firmware 3.1.0.0.3.18 was integrated for IP portal DK103(P).
- Firmware 3.1.0.0.5.18 was integrated for models DS03M(P), DS05M(P), DS06 and DS06M.

New features

- It is possible to open the door from an incoming call notification.
- Devices may be connected via networks with prohibited Ping requests.
- A bug reporter application was added to Intercom installation package.

Version 2.2.7.4 (23.12.2016)

Improvements

- Device SD card records search and playback were improved:
  - record search is performed faster;
  - information about records type and quantity is displayed during the search;
  - background preview loading was added for records in the list.

Version 2.2.6.4 (29.11.2016)

Integration

- Intercom model DS06M was integrated with firmware 3.1.0.0.4.18.6.
- Three-channel controller NC311P was integrated.

New features

- Input contacts state change registration in the application event log for all connected clients was added (for devices with firmware version 3.1.0.0.5.18.6 and higher).

Version 2.2.5.9 (31.10.2016)

Integration

- Firmware 3.1.0.0.4.18 (build date 18.10.2016) was integrated for models DS03M(P), DS05M(P), DS06.
- Firmware 3.1.0.0.4.18 (build date 18.10.2016) was integrated with CamDrive support for model DS05M(P).

Version 2.2.4.6 (22.09.2016)

Integration

- Firmware 3.1.0.0.4.18.54 was integrated for model DS06.

Version 2.2.3.6 (28.07.2016)

Integration

- Intercom model DS06 was integrated with firmware 3.1.0.0.4.18.

SEC.RU | Короткий путь к информации Скачано с sec.ru

Version 2.2.2.10 (06.06.2016)

New features

- Media stream option (Main/Substream) was added to device connection parameters.
- The application's Call Log can be now used for device SD card records playback and saving.

Version 2.2.1.8 (27.04.2016)

Integration

- Firmware 3.1.0.0.3.18 was integrated for models DS03M(P) and DS05M(P).
- Intercom model S03M was integrated with firmware 3.1.5.0.4.18.

Version 2.2.0.15 (20.02.2016)

Integration

- IP portal DK103(P) was integrated with firmware 3.1.0.0.1.18.

New features

- Video recording functionality was added:
  - recording by call;
  - recording by user request;
  - video playback in the call log window.

Version 2.1.2.10 (29.12.2015)

Integration

- Firmware 3.1.0.0.2.18 was integrated for model DS05M(P).

Version 2.1.1.6 (02.12.2015)

- Bug fixes and stabilization.

Version 2.1.0.12 (16.11.2015)

Integration

- Intercom model DS05M(P) was integrated.

New features

- The call log was added:
  - automatic snapshot series creation by the call;
  - snapshot creation by user request;
  - log archive browsing and snapshot series playback in the call log window.

Version 2.0.0.2 (28.08.2015)

Integration

- Door stations supporting up to three alarm outputs were integrated.
- Firmware 3.1.0.0.1.18 was integrated for model DS03M(P).

New features

- Support for simultaneous interaction with several door stations was added:
  - simultaneous addition of several door stations to BEWARD Intercom;
  - displaying the list of added door stations in a window above the system tray icon;
  - simultaneous video stream playback from several door stations in separate windows;

SEC.RU | Короткий путь к информации Скачано с sec.ru

    - audio stream playback from the selected door station;
    - a snapshot is displayed in the video playback area while the video stream is loading.
- Call notifications have been modified:
    - snapshots taken at the moment when a guest presses the call button have been added into the incoming and missed call notifications;
    - each missed call can have a separate notification;
    - it is possible to view all missed calls since the application start using the context menu of the system tray icon.

Version 1.0.12.9 (13.03.2015)

- Bug fixes and stabilization.

Version 1.0.11.3 (20.01.2015)

Fixes

- Updated English and Russian log messages and documentation.

Version 1.0.10.5 (29.12.2014)

New features

- Setting "Decode video stream when the application is hidden" was added to "Application settings" tab. It allows to receive video from the camera instantly when opening the application from the system tray.

Changes

- Setting "Keep video streaming when the application window is hidden" was moved to "Application settings" tab.

Version 1.0.9.10 (10.12.2014)

Integration

- Firmware 2.1.0.1.55.18 was integrated for model DS03M(P).

New features

- English user interface.
- English user operation manual.
- Language selection during installation (Russian, English).
- Device settings can now be changed via the application interface.
- Sounds played on the door panel can now be changed via the application interface.

Version 1.0.7.9 (17.10.2014)

New features

- Application window is hidden automatically after talk.
- Added missed calls notification.

SEC.RU | Короткий путь к информации Скачано с sec.ru